

Locbit, Inc. TEST REPORT

SCOPE OF WORK

OPENADR 2.0A VEN - HTTP PULL - LOCBIT 1.0 - PASSED

REPORT NUMBER

1005110152PLS-001

ISSUE DATE


24-May-2018

PAGES

5

DOCUMENT CONTROL NUMBER

GFT-OP-10h (6-July-2017) © 2018 INTERTEK





TEST REPORT

4683 Chabot Drive, Suite #200 Pleasanton, CA, 94588

Telephone: 925-484-6491 www.intertek.com

Ph: 858-304-1151

24-May-2018 Intertek Report No. 1005110152PLS-001 Intertek Project No. GIN # (G103522699)

Boiam Spassov Locbit, Inc. 9750 Miramar Road, Suite 133, San Diego, CA 92126 spassov@locbit.com

Subject: OpenADR 2.0A VEN-HTTP Pull test results of the LOCBIT V1.0

Dear Mr. Boiam Spassov,

This test report for the *LOCBIT V1.0* represents the results of our evaluation of the above referenced product(s) to the requirements contained in the following standards:

METHODS

DESCRIPTION OF TEST METHODS AND STANDARDS
OpenADR 2.0a VEN- HTTP Pull
Test Harness Version 1.1.2

SAMPLES PROVIDED

SAMPLE #	SAMPLE RECEIVED	SERIAL#	DATE	CONDITION
Sample				
	Remote			
	Desktop			
	Connection			

TESTED <23-May-2018>

This report is for the exclusive use of Intertek's Client and is provided pursuant to the agreement between Intertek and its Client. Intertek's responsibility and liability are limited to the terms and conditions of the agreement. Intertek assumes no liability to any party, other than to the Client in accordance with the agreement, for any loss, expense or damage occasioned by the use of this report. Only the Client is authorized to permit copying or distribution of this report and then only in its entirety. Any use of the Intertek name or one of its marks for the sale or advertisement of the tested material, product or service must first be approved in writing by Intertek. The observations and test results in this report are relevant only to the sample tested. This report by itself does not imply that the material, product, or service is or has ever been under an Intertek certification program.

Version: 6-July-2017 Page 2 of 5 GFT-OP-10h



Locbit, Inc.

Intertek Report: No: 1005110152

TEST REPORT

Case Name	Result	Log
E1_0020_TH_VTN	PASS	View Log TraceLog_052318_095127_005.txt
E1_0040_TH_VTN	PASS	View Log TraceLog_052318_095227_942.txt
E1_0060_TH_VTN	PASS	View Log TraceLog_052318_095340_880.txt
E1_0070_TH_VTN	PASS	View Log TraceLog_052318_095511_599.txt
E1_0082_TH_VTN	PASS	View Log TraceLog_052318_095612_380.txt
E1_0086_TH_VTN	PASS	View Log TraceLog_052318_095708_677.txt
E1_0090_TH_VTN	PASS	View Log TraceLog_052318_095905_942.txt
E1_0092_TH_VTN	PASS	View Log TraceLog_052318_100024_536.txt
E1_0094_TH_VTN	PASS	View Log TraceLog_052318_100135_161.txt
E1_0096_TH_VTN	PASS	View Log TraceLog_052318_100236_786.txt
E1_0098_TH_VTN	PASS	View Log TraceLog_052318_100348_661.txt
E1_0100_TH_VTN	PASS	View Log TraceLog_052318_100508_630.txt
E1_0102_TH_VTN	PASS	View Log TraceLog_052318_100623_317.txt
E1_0104_TH_VTN	PASS	View Log TraceLog_052318_100731_067.txt
E1_0110_TH_VTN	PASS	View Log TraceLog_052318_100926_724.txt
E1_0130_TH_VTN	PASS	View Log TraceLog_052318_101022_942.txt
E1_0180_TH_VTN	PASS	View Log TraceLog_052318_101138_224.txt
E1_0190_TH_VTN	PASS	View Log TraceLog_052318_101241_817.txt
E1_0200_TH_VTN	PASS	View Log TraceLog_052318_101502_083.txt
E1_0210_TH_VTN	PASS	View Log TraceLog_052318_101847_567.txt
E1_0220_TH_VTN	PASS	View Log TraceLog_052318_102456_411.txt
E1_0230_TH_VTN	PASS	View Log TraceLog_052318_103047_177.txt
E1_0240_TH_VTN	PASS	View Log TraceLog_052318_104015_239.txt
E1_0250_TH_VTN	PASS	View Log TraceLog_052318_104703_255.txt
E1_0260_TH_VTN	PASS	View Log TraceLog_052318_111443_239.txt



Locbit, Inc.

Intertek Report: No: 1005110152

TEST REPORT

E1_0260_TH_VTN	PASS	View Log TraceLog_052318_112046_005.txt
E1_0260_TH_VTN	PASS	View Log TraceLog_052318_112552_989.txt
E1_0262_TH_VTN	PASS	View Log TraceLog_052318_113314_364.txt
E1_0262_TH_VTN	PASS	View Log TraceLog_052318_114126_364.txt
E1_0262_TH_VTN	PASS	View Log TraceLog_052318_114832_942.txt
E1_0267_TH_VTN	PASS	View Log TraceLog_052318_115906_099.txt
E1_0267_TH_VTN	PASS	View Log TraceLog_052318_120517_614.txt
E1_0267_TH_VTN	PASS	View Log TraceLog_052318_121222_067.txt
E1_0268_TH_VTN	PASS	View Log TraceLog_052318_122419_317.txt
E1_0268_TH_VTN	PASS	View Log TraceLog_052318_122956_692.txt
E1_0268_TH_VTN	PASS	View Log TraceLog_052318_123927_567.txt
E1_0270_TH_VTN	PASS	View Log TraceLog_052318_125039_458.txt
E1_0280_TH_VTN	PASS	View Log TraceLog_052318_133348_474.txt
E1_0285_TH_VTN	PASS	View Log TraceLog_052318_133631_849.txt
E1_0292_TH_VTN	PASS	View Log TraceLog_052318_133725_317.txt
E1_0297_TH_VTN	PASS	View Log TraceLog_052318_134130_958.txt
E1_0300_TH_VTN	PASS	View Log TraceLog_052318_134421_739.txt
E1_0310_TH_VTN	PASS	View Log TraceLog_052318_135223_161.txt
E1_0320_TH_VTN	PASS	View Log TraceLog_052318_135639_161.txt
E1_0340_TH_VTN	PASS	View Log TraceLog_052318_135747_427.txt
E1_0345_TH_VTN	PASS	View Log TraceLog_052318_140421_958.txt
E1_0360_TH_VTN	PASS	View Log TraceLog_052318_140532_755.txt
E1_0370_TH_VTN	PASS	View Log TraceLog_052318_140801_474.txt
E1_0390_TH_VTN	PASS	View Log TraceLog_052318_141519_583.txt
E1_0392_TH_VTN	PASS	View Log TraceLog_052318_141623_739.txt
S1_1400_TH_VTN	PASS	View Log TraceLog_052318_141731_020.txt



Locbit, Inc.

Intertek Report: No: 1005110152

Yara Layton

Tara Layton

TEST REPORT

S1_1405_TH_VTN	PASS	View Log TraceLog_052318_141825_442.txt
T9_1200	PASS	View Log TraceLog_052318_142149_786.txt
T9_1210	PASS	View Log TraceLog_052318_142354_833.txt

REPORT AUTHORIZED

denne a

Florencio Ponce

Engineer Reviewer